TEXAS WATER COMMISSION



B. J. Wynne, III, Chairman John E. Birdwell, Commissioner Cliff Johnson, Commissioner



John J. Vay, General Counsel

Michael E. Field, Chief Hearings Examiner

Brenda W. Foster, Chief Clerk

Allen Beinke, Executive Director

January 10, 1990

Part



Anthony Robledo, Chief Texas Section Hazardous Waste Management Division U. S. Environmental Protection Agency Region VI - 6H-PT 1445 Ross Avenue Dallas, Texas 75202

Re: Rexene - Pasadena
Solid Waste Registration Number 30486
Permit Application Number 50066
EPA I. D. Number TXD020800371

Dear Mr. Robledo:

Enclosed is an Administrative Notice of Deficiency Response received on December 27, 1989 to the Part B hazardous waste permit application for the subject facility.

Comments should be addressed to Kyle Shelton at (512) 463-8278.

Sincerely,

Talurt Trydawn fur Cheryl A. Wilson, Head

Reports and Information Management Unit

Hazardous and Solid Waste Division

BB:am

Enclosure

cc: Gerald Hord, Regional Manager, Texas Water Commission Southeast Region - Deer Park Office Lawrence E. Pewitt, P. E., Permits Division, Texas Air Control Board, 6330 Highway 290 East, Austin, Texas 78723



POST OFFICE BOX 3986 • ODESSA, TEXAS 79760 • 915-333-7200

December 21, 1989

Mr. Kyle Shelton
Permits Section
Hazardous and Solid Waste Division
Texas Water Commission
P. O. Box 13087 Capitol Station
Austin, Texas 78711

Re: Pasadena Facility

Administrative Completeness

Industrial Solid Waste Registration No. 30486

Proposed Permit No. HW-50066

Dear Mr. Shelton:

As requested in Mr. Minor Hibbs letter dated December 1, 1989, Rexene Products Company is submitting the following information:

The original and four copies of the signed and notarized signature page is included as Attachment I to this letter.

Included as Attachment II to this letter is an updated, revised list of adjacent landowners. This list is labeled "Attachment B-1". Also included under Attachment II are two drawings which reference the attached list of landowners. These drawings are labeled "Attachment B-2" and "Attachment B-3". An original and four copies of the landowners list and the drawings are being provided.

I hope this information will allow the Part B Application for the Pasadena Facility to be considered administratively complete and allow the review process to continue. I sincerely apologize for the delay in providing this information to the T.W.C. and any inconvenience it may have caused.

If there are any questions or if additional information is required concerning this matter, please feel free to contact me at 915/333-8205.

FS 2700

Sincerely,

S. A. Melton, Specialist

S. A. Melton, Specialist Environmental Regulatory Affairs REXENE PRODUCTS COMPANY

SAM/sj (SAM-166³89) ¼ Mys Slow

Mr. m. Bill F. W.

8688 13

EXECUTIVE DIRECTOR TEXAS WATER COMMISSION

ATTN: Hazardous and Solid Waste Division

P.O. Box 13087, Capitol Station

Austin, Texas 78711

FOR DEPARTMENT USE ONLY
Application No
Permit No
Adm. Review By
Administratively
Complete
Copies Sent:

INDUSTRIAL HAZARDOUS WASTE PART B PERMIT APPLICATION

Please refer to the Instructions when preparing this application.

I. GENERAL	INFORMATION
------------	-------------

	(Individual, Co	orporation, or Other	Legal Entity Name)	
Address	:P. O. Box 39	86	,	
City:	0dessa	State:Texas	Zip Code: 79760	
Telepho	ne Number: (915) 3	33-7200		
	annliantion is sub		a corporation, please	

- B. 1. List those persons or firms, including a complete mailing address and telephone number, authorized to act for the applicant during the processing of the permit application.
 - 1) L. N. Anderson, Executive Vice President of Manufacturing/Technical
 - 2) M. P. Hughes, Vice President of Environmental, Health and Safety address: Rexene Products Company

P. O. Box 3936

Odessa, Texas 79760

Telephone: (915) 333-7200

2. If the application is submitted by a corporation or by a person residing out of state, the applicant must register an Agent in Service or Agent of Service with the Texas Secretary of State's office and provide a complete mailing address for the agent. The agent must be a Texas resident.

CT Corporation 1601 Elm Street Dallas, Texas 75201 (214) 979-1172

 List the individual and his/her mailing address that will be responsible for causing notice to be published in the newspaper.
 Same as applicant

I, L. N. Anderson		vaidom±
(Name)	(Title)	stoent
certify under penalty of law that I have information submitted in this document a inquiry of those individuals immediately believe the submitted information is tru are significant penalties for submitting of civil penalty and criminal fines. Signature: L. N. Anderson, Executive	nd all attachments and that, based on responsible for obtaining the inform e, accurate and complete. I am aware false information, including the pos	my ation,]

TO BE COMPLETED BY THE APPLICANT IF THE APPLICANT.	APPLICATION IS SIGNED BY AN AGENT FOR	THE
(Print or Type Name)	designate(Print or Type Name)	
as my agent and hereby authorize said age		
a Texas Water Code or Texas Solid Waste of that I am responsible for the contents of by my agent in support of the application conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of any permit which might be in the conditions of the cond	this application, for oral statement a, and for compliance with the terms	te missen
	Printed or Typed Name of Applic or Principal Executive Off	ant
	Signature	
(Note: Application Must Bear S	ignature & Seal of Notary Public)	
SUBSCRIBED AND SWORN to before me by the		
L. N. Anderson on this 15th d		
	·	89
My commission expires on the 10th da	y of <u>September</u> , 19_	93
ANT POS	Carolin J. Fries	,
CAROLYN J. TRIPP Notary Public, State of Texas My Commission Expired 1 - 10 - 413	Notary Public in and for THE STATE OF TEXAS	
OF 1	ECTORCounty,	Texas

ATTACHMENT B-1

ADJACENT LAND OWNERS


REXENE PRODUCTS COMPANY - BAYPORT FACILITY

- 1. ATLANTIC RICHFIELD COMPANY (ARCO)
 3500 Entex Bldg.
 1200 Milam
 Houston, Texas 77002
- 2. SOUTHERN IONICS TEXAS 12901 Bay Park Rd. Pasadena, Texas 77507
- 3. HOECHST-CELANESE CHEMICAL GROUP, INC. 1250 W. Mockingbird Lane Dallas, Texas 75247
- 4. OXY PETROCHEMICALS, INC. Five Greenway Plaza, Suite 2500 Houston, Texas 77046
- 5. ICI AMERICAS, INC.
 New Murphy Rd. and Concord Pike
 Wilmington, Delaware 19897
- 6. CHEVRON USA, INC.
 P. O. Box 5050
 San Ramon, California 94583-0905
- A. EXXON COMPANY, USA
 P. O. Box 4160
 Houstond, Texas 77252-4160
- B. CIRCLE K COMPANY, INC.
 Karl Eller
 P. O. Box 52085
 Phoenix, Arizona 85072-2085
- C. FAIRMONT PARK JOINT VENTURE C/O GRAY ENTERPRISES P. O. Box 638 Baytown, Texas
- J. P. SERVICE CENTERJ. P. JacksonP. O. Box 7018Pasadena, Texas 77508


- E. REID ELEMENTARY SCHOOL
 LAPORTE INDEPENDENT SCHOOL DISTRICT
 724 S Broadway
 LaPorte, Texas 77571
- F. BRYON E. COOPER, JR. 9930 Parkway LaPorte, Texas 77571
- G. DENNIS M. & ELIZABETH CASTO 9934 Parkway LaPorte, Texas 77571
- H. MICHAEL J. FISHBECK 9938 Parkway LaPorte, Texas 77571
- I. ADMIN VETERANS AFFAIRS 2515 Murworth Dr. Houston, Texas
- J. CROOK JERRY W. & ANNA N. 1041 Fairway Clovis, New Mexico
- K. GOOD ROBERT A. & VERA M. 9950 Parkway LaPorte, Texas 77571
- L. FAIRMONT PARK JOINT VENTURE C/O GRAY ENTERPRISES P. O. Box 638 Baytown, Texas
- M. FAIRMONT PARK JOINT VENTURE C/O GRAY ENTERPRISES P. O. Box 638 Baytown, Texas
- N. FAIRMONT PARK JOINT VENTURE C/O GRAY ENTERPRISES P. O. Box 638 Baytown, Texas

ATTACHMENT B-2

ATTACHMENT B-2



TA - RHOLL PARKUAY





November 4, 1988

Executive Director
Texas Water Commission
P. O. Box 13087 Capitol Station
Austin, Texas 78711

Re: Addendum to Part B Permit Application Draft Permit HW 50066

Dear Sir:

With this letter Rexene Products Company is submitting an addendum to its original Part B Permit Application submitted in 1985 for our Pasadena facility (N.O.R. 30486). The addendum includes the Section VIII - Releases From Solid Waste Management Units and Corrective Action information required by the Hazardous and Solid Waste Amendments (HSWA) of 1984.

If you have any questions or need additional information concerning the addendum, please feel free to contact me at 915-333-8562.

Sincerely,

D. R. Smith, Director

Environmental Regulatory Affairs

DRS/sj (DRS-238-88)

TABLE VIII-2--HAZARDOUS WASTE MANAGEMENT FACILITY UNITS

	Container Storage Area "Drum Storage Area"	(Surface) Tank Storage/Processing "Fouled Xylene Tank"	Open Controlled Incineration Area	Verbal Description
•	ယ	N	-	Facil.
	S01	T01	T03	Process Code (2)
	35750 gal. 650 drums	42000 gal.	350 gal.	Capacity Unit of Measure (3)
	A / _/ 82 _	A / _ / 76	A_/_/_/ /_/_/ C/_/ 85	Status, Date and Years in Service (4)
970020-Chromate Bearing Solids, 111050-Esters, Organic (high boiling), 910010-Heptane, 910620-Isopropyl Alcohol, 155260-Hexane, Isopropanol & Polypropylene Solids	6 914740-Ignitable Wastes, 181510- Hydrocarbon Contaminated Absorbent, 910070-Hexane, 949510-Titanium Trichlo- ride in White Mineral Oil, 919150-Laboratory	12 916350-Xylene with Solid Polypropylene	916000-Sodium in Mineral Oil, 270490-Contaminated Soil, 910620-Isopropyl Alcohol, 2 910070-Hexane, 109640-Methanol & Water	Wastes Managed Waste Code or Verbal Description
	Carbon Disulfide, Methylene Chloride, Chromium & Compounds	None	None	Wastes Managed in the Facility Unit Constituents listed in Appendix VIII Code or 40 CFR 261 Description contained in the waste
				Release
				Comments

TABLE VIII-2--HAZARDOUS WASTE MANAGEMENT FACILITY UNITS

(Surface) Fank 5 Storage "Slop Oil Tank"	Thermal Processing 4 Unit "Reactor Burn Pit"	Container Storage Area (cont. "Drum Storage Area" (continued)	Verbal Facil. Description No.(1)
VO.	Т04) 1	Process Code (2)
8400 gai.	75000 gal. 40000 lb/hr		Capacity Unit of Measure (3)
A / _/ 76 12	A / / 76 12 1 / / /		Status, Date and Years in Service (4)
with Hexane, 110490-Lubricating Oil	Wastes, 949510-Titanium Trichtoride (60%) in White Mineral Oil, 111050-Esters, Organic (High Boiling), 910010- Heptane, 910620-Isopropyl Alcohol, 910070-Hexane, 916000-Sodium in Mineral Oil	propylene Solids, 970260-Ash of Sodium in Mineral Oil, 270960-Dessicant, 179740-Dry Paint, 280250-Roofing Pitch, 152310-Oil Sludge, 180440-Grease	Wastes Managed Waste Code or Verbal Description
None	None		naged in the Facility Unit Constituents listed in Appendix VIII 40 CFR 261 contained in the waste
			Release Y
			Comments

TABLE VIII-2-HAZARDOUS WASTE MANAGEMENT FACILITY UNITS

		"Luwa Pan Area"	Container Storage	"Fouled Naphtha/ Xylene Tank"	(Surface) Tank		"Fouled Naphtha/ Xylene Tank"	(Surface) Tank	Tank"	"Peroxide Neutralization	(Surface) Tank	Verbal Description
			-		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			8			6	Facil.
			S01		To1			T01			T01	Process Code (2)
			1650 gal.		17640 gal.		-	17640 gal.			550 gal.	Capacity Unit of Measure (3)
	c_/_/_	1 / 82 3	A_/_/		A / _/ 88 1			A_/_/_	c//	· / / /	A / / 78 10	Status, Date and Years in Service (4)
ride in White Mineral Oil	148870-Titanium Tetrachlo-	ride in White Mineral Oil,	949510-Titanium Trichlo-	Polyethylene	916350-Xylene with			950970-Naphtha Sludge	Hexane	Neutralized with Caustic /	916360-Peroxide, Organic,	Wastes Managed in the Facility Unit Constituents in Appendix Waste Code or Verbal Description contained in the
			None		None			None			None	n the Facility Unit Constituents listed in Appendix VIII 40 CFR 261 contained in the waste
1			 ×	1	 ×			 ×		1	 ×	Release
				Jan. 88	Re-opened							Comments

TABLE VIII-1A -- SOLID WASTE MANAGEMENT FACILITY UNITS


Retention Pond	Storm Water	Clarifier	Processing Oil/Water Separator Skimming Basin	Verbal Description (Surface) Tank
	ი	6	>	Facil. No.(1)
	Т04	T01	D83	Process Code (2)
	t_ !	3,150 gal.	0	Capacity Unit of Measure (3)
° _ / _ /				Status, Date and Years in Service (4)
				=
Run-off Water	Run-off Water Uncontaminated Storm	Run-off Water Uncontaminated Storm	Sludge Uncontaminated Storm	Wastes Managed in the Facility Unit Constituents in Appendi Waste Code or 40 CFR Verbal Description contained in t
	None	None	None	n the Facility Unit Constituents listed in Appendix VIII 40 CFR 261 contained in the waste
				Release
				Comments

TABLE VIII-1A-- SOLID WASTE MANAGEMENT FACILITY UNITS

Storage Tank	Satellite Storage Area Underground	Polypropylene	Polyethylene Satellite Storage Area	Fuel Oil Collection Pit	Verbal Description
	ဓ	П	rn .	D	Facil.
	T01	S01	S01	T01	Process Code (2)
	375 gal.	2200 gal.	5500 gal.	4700 gal.	Capacity Unit of Measure (3)
	C / / 76 1	C / / 81		A//	Status, Date and Years in Service (4)
	12 110490-Oil, Lubricating	7 110490-Oil, Lubricating	110490-0	149820-Oil & Water 3 Sludge	Wastes Managed in the Facility Unit Constituents in Appendi Waste Code or Verbal Description Waste Contained in t
	None	None	None	None	n the Facility Unit Constituents listed in Appendix VIII 40 CFR 261 contained in the waste
					Release N
				To be closed	Comments

TABLE VIII-1A -- SOLID WASTE MANAGEMENT FACILITY UNITS


	Polypropylene Dumpster"	Storage Area "Atactic	Container	Verbal Description
		. ,	Ξ	Facil.
			S01	Process Code (2)
		yards	60 cubic	Capacity Facil. Process Unit of No.(1) Code (2) Measure (3)
	C / _ / 80		A//	Status, Date and Years in Service (4)
Į.	4		 -	
		pylene	180970-Atactic Polypro-	Wastes Managed in the Facility Unit Constituent in Append Waste Code or Verbal Description Contained in the Facility Unit Constituent Cons
			None	n the Facility Unit Constituents listed in Appendix VIII 40 CFR 261 contained in the waste
1			×	Release
				Comments




ALL COPYRIGHTS RESERVED On Not Scale This Drawing.

1984 IT CORPORATION

INTERNATIONAL TECHNOLOGY CORPORATION





- Isyon M. Andorson	Executive Vice President,	
I, Lavon N. Anderson		
(Name)	(Title)	
certify under penalty of law that I have p	ersonally examined and am familiar with	-1
information submitted in this document and	all attachments and that hased on my	the
inquiry of those individuals immediately r	esponsible for obtaining the information	
believe the submitted information is true,	accurate and complete. I am assess the	n,
are significant penalties for submitting f	alse information including the possible	re
of civil penalty and criminal fines.	including the possible	110)
Ja (1) 2	Me with	
Signature: // Kullus	Date: November 4, 1988	
TO BE COMPLETED BY THE APPLICANT IF THE AP	PLICATION IS SIGNED BY AN AGENT FOR THE	•
APPLICANT.	The second of th	
hereby d	esignate	
(Print or Type Name)	(Print or Type Name)	
as my agent and hereby authorize said agen		
additional information as may be requested any hearing or before the Texas Water Commatant Texas Water Commatant I am responsible for the contents of my my agent in support of the application, conditions of any permit which might be is:	ission in conjunction with this request sposal Act permit. I further understand this application, for oral statements given and for compliance with the terms and	for
	Printed or Typed Name of Applicant	
•	or Principal Executive Officer	
		·············
	of filmelpar Executive Officer	
	of filmcipal Executive Office)	
• • • • • • • • • • • • • • • • • • •		•
	Signature	*
(Note: Application Must Bear Sig		
	Signature gnature & Seal of Notary Public)	· · ·
UBSCRIBED AND SWORN to before me by the sa	Signature gnature & Seal of Notary Public)	· · · ·
	Signature gnature & Seal of Notary Public)	· · · ·
UBSCRIBED AND SWORN to before me by the sa	Signature gnature & Seal of Notary Public) aid v of November, 19 88	· · · ·
UBSCRIBED AND SWORN to before me by the sa Lavon N. Anderson on this 4th day	Signature gnature & Seal of Notary Public) aid v of November, 19 88	
UBSCRIBED AND SWORN to before me by the saturation on this 4th day y commission expires on the 5th day	Signature gnature & Seal of Notary Public) aid v of November, 19 88	· · · ·
UBSCRIBED AND SWORN to before me by the saturation N. Anderson on this 4th day y commission expires on the 5th day	Signature gnature & Seal of Notary Public) aid of November , 19 88 of October , 19 90 Sita Sweeden	
UBSCRIBED AND SWORN to before me by the saturation on this 4th day y commission expires on the 5th day	Signature gnature & Seal of Notary Public) aid v of November, 19 88	
UBSCRIBED AND SWORN to before me by the saturation N. Anderson on this 4th day y commission expires on the 5th day NITA SWEEDEN Notary Public, State of Texas	Signature gnature & Seal of Notary Public) aid of November , 19 88 of October , 19 90 Sita Sweeden	

by my agent in support of th conditions of any permit whi	Pr In Must Bear Signature Ore me by the said Itis 4th day of	r compliance with the te	pplicant re Officer 1988 1990
(Note: Applications of any permit whing the subscribed AND SWORN to be for the Lavon N. Anderson on the subscribed and subscribed and sworn on the subscribed and sworn on the subscribed and sworn on the subscribed and subscribed and sworn on the subscribed and	on Must Bear Signature ore me by the said is 4th day of	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv Signature & Seal of Notary Public November	pplicant of Officer 1988
(Note: Applications of any SWORN to before	on Must Bear Signature	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv Signature & Seal of Notary Public November	pplicant of Officer 1988
by my agent in support of th conditions of any permit whi	n Must Bear Signature	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv	pplicant of Officer
by my agent in support of th conditions of any permit whi	ch might be issued ba	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv	pplicant of Officer
by my agent in support of th conditions of any permit whi	ch might be issued ba	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv	pplicant of Officer
by my agent in support of th	ch might be issued ba	r compliance with the te sed upon this applicatio inted or Typed Name of A or Principal Executiv	rms and n.
by my agent in support of th	ch might be issued ba	r compliance with the te sed upon this applicatio inted or Typed Name of A	rms and n.
by my agent in support of th	ch might be issued ba	r compliance with the te sed upon this applicatio inted or Typed Name of A	rms and n.
by my agent in support of th	e application, and fo ch might be issued ba	r compliance with the te	rms and
by my agent in support of th	e application, and fo ch might be issued ba	r compliance with the te	rms and
(Print or Type Name) as my agent and hereby autho additional information as ma any hearing or before the Te a Texas Water Code or Texas that I am responsible for the	y be requested by the xas Water Commission Solid Waste disposal e contents of this ap	Commission; and/or appe in conjunction with this Act permit. I further u plication, for oral stat	ar for me at request for inderstand
I	hereby designat	(Brint or Tune News)	
TO BE COMPLETED BY THE APPLI APPLICANT.	CANT IF THE APPLICATION	ON IS SIGNED BY AN AGENT	FOR THE
		• • • • • • • • • • • • • • • • • • • •	
Signature: / / / / / / / / / / / / / / / / / / /	D.	November 4, 198	
Solo		Narrombon / 100	00
are significant penalties for of civil penalty and crimina	r submitting false in	formation, including the	possibility
inquiry of those individuals believe the submitted inform	ation is true, accurat	te and complete. I am av	ware there
	s document and all at	tachments and that, based	d on my
information submitted in this		(Title)	
(Name) certify under penalty of law information submitted in thi			
certify under penalty of law information submitted in thi		xecutive Vice President, anufacturing/Technical	-

ADJACENT LANDOWNERS

El Paso Polyolefins - Bayport Rexene Plant

- 1 Housing Development Information to be supplied later.
- 2 ATLANTIC RICHFIELD COMPANY (ARCO)
 3500 Entex Bldg.
 1200 Milam
 Houston, Texas 77002
- THE QUAKER OATS COMPANY P. O. Box 3514 Chicago, Illinois 60654
- 4 CELANESE CHEMICAL COMPANY, INC. 1250 W. Mockingbird Lane Dallas, Texas 75247
- (5) ICI AMERICAS, INC.
 New Murphy Road
 Wilmington, Delaware 19897
- 6 FRIENDSWOOD DEVELOPMENT COMPANY
 P. O. Box 2180
 Houston, Texas 77001
- An oil field exclusion in the industrial property dedicated to the Bayport Complex.

11 174

El Paso Products Co.-El Paso Polyolefins-Bayport Regene Plant

номі опісь желмого, упетна Annaled to and made a part of Congress tale from one Conjugation ______ (One ren Policy P-OD-30)

DXHIBIT "A"

TRACT 1:

Being a tract or parcel of land containing 509.2839 acres located in the William M. Jones Survey, A-482 and the George B. McKinstry League, A-47, Harris County, Texas, and being more particularly described by metes and bounds as follows (all bearings referenced to the Texas Coordinate System, South Central Zone):

BESINTING at Rod 2764, said rod marking the intersection of the most westerly line of a 230.00 foot wide Harris County Flood District Fee Strip as recorded in Volume 8260, Page 124, Deed Records, Marris County Texas the the most southerly line of Fairmont Parkway (250.00 feet wide);

THEMICE S 07°15'39" E, (previously called S 05°20'00" E), with the westerly line of said 230 foot wide Harris County Flood Control Fee Strip, 1124.97 feet to Rod 2765 for a corner;

THERCE continuing with said westerly line, S 34°59'39" E, (previously called S 33°04'00" E), 1266.82 feet to Rod 2766 for a corner;

THEREE leaving said westerly line, S 55°00'21" W, 300.00 feet to Rod 2767 for a corner;

THENCE S 34°59'39" E, at 89.72 feet pass the common line of the aforementioned William M. Jones Survey and the George B. McKinstry League, and continuing for a total distance of 686.37 feet to Rod 2768 for a corner in the most westerly line of a 100.00 foot wide corridor;

THENCE with the westerly line of said 100.00 foot wide corridor, S 15°06'49" W, 3186.99 feet to Rod 2769 for a corner, said rod being in the easterly boundary of that certain Clear Lake City Water Authority tract described in Volume 5112, Page 59, Deed Records, Harris County, Texas;

THERCE with said easterly boundary S 88°03'59" W, (previously called West), 3289.15 feet to Rod 2770 for a corner;

THE CE continuing with said easterly boundary N 01°56'03" W, (previously called North), at 3506.30 feet pass the aforementioned common line of the William M. Jones Survey and the George B. McKinstry League and continuing for a total distance of 5813.56 feet to Rod 2762 for a corner in the aforementioned southerly line of Flarmont Parkway;

THEMICE continuing with said easterly boundary N 01°56'03" N, 124.52 feet to a point for corner;

THENCE leaving said easterly boundary N 86°49'59" E, 3301.86 feet to a roint for corner in the aforementioned westerly line of a 230.00 foot wide Harris County Flood Control Drainage Fee Strip;

THRUCE with said westerly line, S 07°15'39" E, 41.65 feet to the FORT OF BEGINNING and containing 509.2839 acres of land including 3.7096 acres now in Fairmont Parlamy. Laurers Title Insurance Corporation

Countersigned at HOUSTON, TEXAS

this 10th day of

LAWYERS TITLE COMPANY OF HOUSTON

Secretary.

butterng colores Authorized Other or Agent A tract of land containing 135.21 acres, more or less, located in the George B. McKinstry League, A-47, Harris County, Texas being more particularly described as follows (All hearings referenced to the Texas Coordinate System, South Central Zone):

Beginning at the Southwest corner of that certain Tract one described in Deed dated March 14, 1974 and recorded in Film code 103-11-868, which corner is called Rod 2770;

Thence N01° 56' 03" W-a distance of 1650 feet;
Thence N88° 03' 59" E a distance of 3850 feet
more or less to the East line of said Tract one;
Thence S15° 06' 49" W a distance of 1780 feet
more or less to the South line of said Tract one;
Thence S88° 03' 59" W 3289 feet the point of the beginning.

ATTACHMENTS D

Verbal Description of Waste Waste Xylene w/Propylene Solids		
Process (see last column in Table III-1) 2821 - Po	olypropylene	
TDWR Sequence Number of Waste (if assigned) 003	3	
Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.		
Lagoon/Pond (unlined)	Landfarm	
Lagoon/Pond (lined)	Landspreading Area	
Basin (earthen, above-grade lined)	Spray Irrigation Area	
Basin (earthen, above-grade unfined)	Flood Irrigation Area	
Basin (earthen, below-grade lined)	Septic Tank/Drain Field	
Basin (earthen, below-grade unlined)	Injection Well	
Basin (concrete, above-grade lined)	X Tank (surface storage)	
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)	
Basin (concrete, below-grade fined)	Tank (surface processing)	
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)	
Basin (other)	Tank (other)	
Pit (lined)	Drum Storage Area	
Pit (unlined)	Other Container Storage Area	
Incinerator	Other Container Storage Area	
Open Controlled Incineration Area	Other Container Storage Area (specify type of	
	of container	
Boiler (energy-producing)		
Landfill (sanitary)	Waste Pile Storage Area	
Landfill (surface, open)	X Other (specify Transported off-site	
Landfill (other)	in bulk.	

Verbal Description of Waste Waste IPA/Hexane Solvent 2/PP Fines

2821 - Polypropylene Process (see last column in Table III-1) 012 TDWR Sequence Number of Waste (if assigned) Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed. __ Lagoon/Pond (unlined) ___ Landfarm Lagoon/Pond (lined) ____ Landspreading Area ___ Basin (earthen, above-grade lined) ____ Spray Irrigation Area ____ Basin (earthen, above-grade unlined) ____ Flood Irrigation Area _____ Basin (earthen, below-grade lined) __ Septic Tank/Drain Field _ Basin (earthen, below-grade unlined) _ Injection Well Basin (concrete, above-grade lined) X Tank (surface storage) ___ Basin (concrete, above-grade unlined) ____ Tank (sub-surface storage) ____ Basin (concrete, below-grade lined) __ Tank (surface processing) _____ Basin (concrete, below-grade unlined) __ Tank (sub-surface processing) __ Basin (other) __ Tank (other) ___ Pit (lined) ____ Drum Storage Area ____ Pit (unlined) ____ Other Container Storage Area ____ Incinerator ____ Other Container Storage Area Open Controlled Incineration Area ____ Other Container Storage Area (specify type of of container___ ____ Boiler (energy-producing) _ Waste Pile Storage Area ____ Landfill (sanitary) X Other (specify Transported off-site ____ Landfill (surface, open)

in bulk

___ Landfill (other)

Verbal Description of Waste Waste $TiCl_3$ in Mineral Oil

1 rocess (see last column in Table III-1) 2821 - P	olypropylene •
TDWR Sequence Number of Waste (if assigned) 01	3
Indicate the facility components used for storage/procenumber of such facility components by which this was	essing/disposal of the above-specified waste by entering the te is managed.
Lagoon/Pond (unlined)	Landfarm
Lagoon/Pond (lined)	Landspreading Area
Basin (earthen, above-grade lined)	Spray Irrigation Area
Basin (earthen, above-grade unlined)	Flood Irrigation Area
Basin (earthen, below-grade lined)	Septic Tank/Drain Field
Basin (earthen, below-grade unlined)	Injection Well
Basin (concrete, above-grade lined)	Tank (surface storage)
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)
Basin (concrete, below-grade lined)	Tank (surface processing)
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)
Basin (other)	Tank (other)
—— Pit (lined)	X_ Drum Storage Area
Pit (unlined)	Other Container Storage Area
Incinerator	Other Container Storage Area
Open Controlled Incineration Area	Other Container Storage Area (specify type of
	of container
Boiler (energy-producing))
Landfill (sanitary)	Waste Pile Storage Area
Landfill (surface, open)	X Other (specify transported off-site
Landfill (other)	in drume

Verbal Description of Waste Waste Sodium In Mineral Oil		
Process (see last column in Table III-1) 2821 - Polypropylene		
TDWR Sequence Number of Waste (if assigned)	015	
Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.		
Lagoon/Pond (unlined)	Landfarm	
Lagoon/Pond (lined)	Landspreading Area	
Basin (earthen, above-grade lined)	Spray Irrigation Area	
Basin (earthen, above-grade unlined)	Flood Irrigation Area	
Basin (earthen, below-grade lined)	Septic Tank/Drain Field	
Basin (earthen, below-grade unlined)	Injection Well	
X Basin (concrete, above-grade lined)	Tank (surface storage)	
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)	
Basin (concrete, below-grade lined)	Tank (surface processing)	
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)	
Basin (other)	Tank (other)	
Pit (lined)	X Drum Storage Area	
Pit (unlined)	Other Container Storage Area	
Incinerator	Other Container Storage Area	
X Open Controlled Incineration Area	Other Container Storage Area (specify type of	
	of container	
Boiler (energy-producing)		
Landfill (sanitary)	Waste Pile Storage Area	
Landfill (surface, open)	X Other (specify transported off-site in	
Landfill (other)	Bio San Stream to GCWDA	

Verbal Description of Waste Soil, Chromate of	ontaminated	
Process (see last column in Table III-1) Cooling Tower		
TDWR Sequence Number of Waste (if assigned) 027		
Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.		
Lagoon/Pond (unlined)	Landfarm	
Lagoon/Pond (lined)	Landspreading Area	
Basin (earthen, above-grade lined)	Spray Irrigation Area	
Basin (earthen, above-grade unlined)	Flood Irrigation Area	
Basin (earthen, below-grade lined)	Septic Tank/Drain Field	
Basin (earthen, below-grade unlined)	Injection Well	
Basin (concrete, above-grade lined)	Tank (surface storage)	
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)	
Basin (concrete, below-grade lined)	Tank (surface processing)	
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)	
Basin (other)	Tank (other)	
Pit (lined)	X_ Drum Storage Area	
Pit (unlined)	Other Container Storage Area	
Incinerator	Other Container Storage Area	
Open Controlled Incineration Area	Other Container Storage Area (specify type of	
	of container	
Boiler (energy-producing))	
Landfill (sanitary)	Waste Pile Storage Area	
Landfill (surface, open)	X Other (specify <u>Transported off-site</u>	
Landfill (other)	in drums.	

Verbal Description of Waste Waste Heptane		
Process (see last column in Table III-1) 2821 - Po	lypropylene	
TDWR Sequence Number of Waste (if assigned) 028		
Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.		
Lagoon/Pond (unlined)	Landfarm	
Lagoon/Pond (lined)	Landspreading Area	
Basin (earthen, above-grade lined)	Spray Irrigation Area	
Basin (earthen, above-grade unlined)	Flood Irrigation Area	
Basin (earthen, below-grade lined)	Septic Tank/Drain Field	
Basin (earthen, below-grade unlined)	Injection Well	
Basin (concrete, above-grade lined)	X Tank (surface storage)	
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)	
Basin (concrete, below-grade lined)	Tank (surface processing)	
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)	
Basin (other)	Tank (other)	
Pit (lined)	Drum Storage Area	
Pit (unlined)	Other Container Storage Area	
Incinerator	Other Container Storage Area	
— Open Controlled Incineration Area	Other Container Storage Area (specify type of	
·	of container	
Boiler (energy-producing))	
Landfill (sanitary)	Waste Pile Storage Area	
Landfill (surface, open)	X Other (specify Transported off-site	
Landfill (other)	in bulk	

Verbal Description of Waste Xylene Satura	ated Polymer	
Process (see last column in Table III-1) 2821 - Polypropylene		
TDWR Sequence Number of Waste (if assigned)	029	
Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.		
Lagoon/Pond (unlined)	Landfarm	
Lagoon/Pond (lined)	Landspreading Area	
Basin (earthen, above-grade lined)	Spray Irrigation Area	
Basin (earthen, above-grade unlined)	Flood Irrigation Area	
Basin (earthen, below-grade lined)	Septic Tank/Drain Field	
Basin (earthen, below-grade unlined)	Injection Well	
Basin (concrete, above-grade lined)	Tank (surface storage)	
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)	
Basin (concrete, below-grade lined)	Tank (surface processing)	
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)	
Basin (other)	Tank (other)	
Pit (lined)	Drum Storage Area	
Pit (unlined)	Other Container Storage Area	
Incinerator	Other Container Storage Area	
Open Controlled Incineration Area	Other Container Storage Area (specify type of	
•	of container	
Boiler (energy-producing))	
Landfill (sanitary)	Waste Pile Storage Area	
Landfill (surface, open)	X Other (specify <u>transported off-site</u> in	
Londfill (ashara)	laylord cartons on trucks	


Verbal Description of Waste Organic Peroxide/Heptane in Vermiculite

Process (see last column in Table III-1) 2821 - Polypropylene

TDWR Sequence Number of Waste (if assigned) 030

Indicate the facility components used for storage/processing/disposal of the above-specified waste by entering the number of such facility components by which this waste is managed.


Lagoon/Pond (unlined)	Landfarm
Lagoon/Pond (lined)	Landspreading Area
Basin (earthen, above-grade lined)	Spray Irrigation Area
Basin (earthen, above-grade unlined)	Flood Irrigation Area
Basin (earthen, below-grade lined)	Septic Tank/Drain Field
Basin (earthen, below-grade unlined)	Injection Well
Basin (concrete, above-grade lined)	Tank (surface storage)
Basin (concrete, above-grade unlined)	Tank (sub-surface storage)
Basin (concrete, below-grade lined)	Tank (surface processing)
Basin (concrete, below-grade unlined)	Tank (sub-surface processing)
Basin (other)	Tank (other)
Pit (lined)	X Drum Storage Area
Pit (unlined)	Other Container Storage Area
Incinerator	Other Container Storage Area
Open Controlled Incineration Area	Other Container Storage Area (specify type of
	of container
Boiler (energy-producing)	
Landfill (sanitary)	Waste Pile Storage Area
Landfill (surface, open)	X Other (specify Transported off-site
Landfill (other)	in drums)



ATTACHMENT E-2

EL PASO POLYOLEFINS CO.


11-11-12-120



PROCESS DESCRIPTION


Xylene, containing dissolved polypropylene from process cleaning operations, is circulated through a reboiler, flash tank, and condenser arrangement to recover xylene for reuse (overheads) while concentrating the polymer in the fouled xylene (bottoms) to approximately 8%. The fouled xylene is pumped into tank lTK-1903, where it is stored until disposed of off-site.

DRUM STORAGE AREA



PROCESS DESCRIPTION


SEVERAL hazardous wastes are stored temporarily on the Hazardous Waste Drum Storage Area. This is a concrete slab of 40 ft. by 60 ft. with a 4" high curb. The slab drains to a 2,000 gallon oil/water separator and to a 2,000 gallon sump. The slab is elevated 9" above grade. Drums of Waste Titanium Chloride in Mineral Oil, Waste Heptane and Chromate Contaminated Soil. When neutralized Organic Peroxide in caustic is generated it will be stored here before off-site disposal.



PROCESS DESCRIPTION

In the past small amounts of sodium, resulting from sodium storage tank cleanouts, were collected in drums containing mineral oil. The drums were then transported to an enclosed storage area via fork truck prior to on-site incineration. This waste is no longer generated.

REACTOR BURN PIT




PROCESS DESCRIPTION

The Reactor Burn Pit is used for emergency dumping of the reactor. It is a 75,000 gallon capacity concrete lined pit equipped with bath steam and water quenching sprays. Rapid water recirculation rate is also provided at a 40,000 lbs. per hour rate.

Aluminum alkyls, pyrophoric cocatalysts used in the polypropylene reaction, are flushed from process equipment with a solvent, to a ground flare where it spontaneously ignites and burns in the presence of air.


The waste water from this unit are sent with the "Bio San" stream to Gulf Coast Waste Disposal Authority's local plant for ultimate treatment and disposal.

(TWQ8 Code: 110490)




PROCESS DESCRIPTION

Liquids pumped from the polypropylene flare knock-out vessel and oils separated from the plant waste water stream are pumped into tank ITK-0401 for storage prior to off-site disposal.



PROCESS DESCRIPTION

The Peroxide Neutralization Tank is no longer used in the Polyethylene Process. It may be used in the future to dispose of Organic Peroxides from the controlled rheology step in the Polypropylene process. Organic Peroxides flushed from Polypropylene process equipment, will be neutralized in vessel IV-2304 with a Sodium Hydroxide and water solution to reduce the active Oxygen in the Peroxide to less than 2%. The mixture is stored in this vessel (IV-2304) until disposed of off-site.



ATTACHMENT G-3

PROCESS DESCRIPTION

The Bayport Polyolefins plant of the El Paso Products Company manufactures Polypropylene. Until June, 1982, this plant also manufactured low density Polyethylene. Attachment G-1 shows a block flow diagram of the Polypropylene plant as it now operates. The section of the Polypropylene plant known as deashing has not been operated since 1981.

Attachment G-2 shows an approximate layout of the plant site including polypropylene, polyethylene, and utilities. The six hazardous waste management units (HWMU) are also shown on this layout.

Attachment G-l shows the raw materials, catalysts and additives being charged to the Polypropylene plant and shows the products, by-products, and wastes generated by the process. All hazardous wastes are now disposed off-site via permitted disposers. The only waste of any class recovered on-site is the spent molecular sieves, which are regenerated and reused. All hazardous and Class I industrial wastes are manifested to the ultimate disposal site.

TDWR 003

The waste Xylene with Polypropylene solids is generated in the Xylene Storage and Recovery Area. The Xylene is used in the Polymerization Reactor Area and is recycled until the Polypropylene solids content builds up to about 8% concentration. The waste Xylene is then collected in the waste

Xylene Tank. After a sufficient quantity of spent Xylene is generated, a permitted hazardous waste hauler transports the hazardous waste material in bulk to a permitted hazardous waste disposer for ultimate disposal.

TDWR 015 The Waste Sodium in Mineral Oil has not been generated since the deashing section was shutdown. There is some material remaining at the plant site in the feed tank. It is planned to clean the feed tank and dispose of this material off-site. At the time the Part A was submitted, this material was being treated on-site before disposal. Sodium is stored in Mineral Oil to prevent reaction with water or moisture in the air. The material was burned in the open incineration area and the residue disposed.

TDWR 013

The waste Titanium Trichloride (TiCl₃) in Mineral Oil is generated in the Catalyst Mixing Area. This material is collected in drums and transported to the Hazardous Waste drum storage area. It is ultimately transported with other drummed wastes to a permitted hazardous waste disposer. This material is stored under oil because it is reactive with the moisture in the air. This material is disposed off-site by permitted disposers.

TDWR 012 The waste Isopropyl Alcohol (IPA) and Heptane Solvent was collected in the Flare Knock Out (KO) pot and transported in bulk to a permitted disposer. This waste has not been generated since the deashing section was shutdown in 1981. However, there is still condensate collected in the Flare Knock Out vessel and pumped to the Slop Oil Tank. This condensate is greatly reduced in volume and contains no IPA since the deashing section was shutdown. The waste in the Slop Oil Tank is considered hazardous due to

ignitability of Xylene and Heptane. It is disposed off-site in bulk.

TDWR 028 The waste Heptane is actually generated in two places. When the electron donor feed tank is cleaned out in the Catalyst Mix Area, spent Heptane containing a high boiling organic ester is generated. A spent Heptane containing Phosphites is generated in the drying and blending area. Both of these wastes are collected in drums and transported to the Hazardous Waste drum storage area. These drums are ultimately transported off-site with other drums for disposal.

TDWR 029

The Xylene Saturated Polymer is not a continuously produced waste. It is the solid chunks of Polypropylene which are washed out of process equipment. This is collected in drums and moved to the Hazardous Waste Drum Storage Area until it can be transported to a permitted disposer.

TDWR 030 The Organic Peroxide in Vermiculite is not yet generated, but may be beginning next year. This is part of a new procedure called controlled reology of Polypropylene. This was the original plan for disposing of Organic Peroxide wastes from controlled rheology. An alternative is to neutralize these organic peroxides in the Peroxide Neutralization Tank previously housed in the Polyethylene Plant. This plan will be clarified as soon as possible next year.

All wastes transported off-site in bulk are transported and handled in closed tanks, pipes, pumps, and vacuum trucks. A-1 wastes transported off-site in drum containers are transported from process to the hazardous waste storage area via forklift trucks, and are transported off-site in drum trailer trucks of the disposers.

TDWR 027 The Chromate contaminated soil is not generated in the Polypropylene process. It is generated from infrequent spills of Chromate in the Additive Mix Area of the Cooling Tower. We do use a low Chromate treatment system. The spill contaminated soil is placed into steel drums and placed in the Hazardous Waste Drum Storage Area. It is transported off-site via truck to a permitted disposer.

ATTACHMENT H

PART A - III-B (2,4) EXPLAINATION OF PAST HAZARDOUS WASTE PROCESSING AND STORAGE ACTIVITIES

There were two activities which were practiced at the time of RCRA Part A submission:

- (1) Storage of hazardous wastes in drums in several conventional drum storage areas in the plant. No proper hazardous waste drum storage area was available at that time.
- (2) Open controlled incineration of reactive wastes to render them nonhazardous.

Since that time both of these practices have been discontinued. A properly constructed hazardous waste drum storage area was completed in 1982. The 500 drums listed as hazardous waste in the Part A were really unidentified wastes. Since that time all hazardous waste drums have been identified and moved to the new hazardous waste drum storage area. Most of the 500 drums reported to be hazardous in the RCRA Part A were identified to be non-hazardous. All of the drums determined to be hazardous wastes have been properly manifested and disposed off-site.

The Cpen Controlled Incineration Area was formerly used to dispose of one hazardous waste and three Class I wastes by burning to render them non-hazardous. The burning took place in a fabricated steel trough in an open area. The hazardous waste burned at that time was Sodium in Mineral Oil (TDWR Seq. No. 015). The Class I wastes burned at that time were Isopropyl Alcohol (IPA) (TDWR Seq. No. 009), Methanol and Water (TDWR Seq. No. 017), and Hexane (TDWR Seq. No. 018). This is indicated both on the Solid Waste Registration and the RCRA Part A Application for El Paso Products. Any Sodium Hydroxide residue was transferred

into the Reactor Burn Pit where neutralization occurred with residual alkyl. The neutral water was then sent to Gulf Coast Waste Disposal Authority in the plant "biosan" stream. The Opened Controlled Incineration Area was permanently shutdown in September 1982.

The Sodium in Mineral Oil is no longer used in the Polypropylene process. However, there is some material still in storage in the plant feed tank. This tank will be cleaned in the future and the waste material properly disposed. The Sodium in Mineral Oil (TDWR Seq. No. 015) will then be dropped from the Solid Waste Registration.

TEXAS WATER COMMISSION

Appreved

B. J. Wynne, III, ChairmanPaul Hopkins, CommissionerJohn O. Houchins, Commissioner



Allen Beinke, Executive Director Michael E. Field, General Counsel Brenda W. Foster, Chief Clerk

July 13, 1989

Anthony Robledo, Chief Texas Section Hazardous Waste Management Division U. S. Environmental Protection Agency Region VI - 6H-PT 1445 Ross Avenue Dallas, Texas 75202

Re: Rexene Corporation - Pasadena Storage/Processing Solid Waste Registration Number 30486 EPA I. D. Number TXD020800371

Dear Mr. Robledo:

Enclosed are revisions to the Part B hazardous waste permit application for the subject facility.

Comments should be addressed to Kyle Shelton at (512) 463-7949.

Sincerely,

Chengo Weson

Cheryl A. Wilson, Head Reports and Information Management Unit Hazardous and Solid Waste Division

BB:am

Enclosure

cc: Lawrence E. Pewitt, P. E., Permits, Texas Air Control Board, 6330 Highway 290 East, Austin, Texas 78723 Mark Gates, Regional Manager, Texas Water Commission Southeast Region - Deer Park Office

REXENE PRODUCTS COMPANY CLOSURE PLAN BAYPORT POLYOLEFINS PLANT SECTION A-3

INDEX

	PAGE NO.
INTRODUCTION	3-1.1
FACILITY 02	3-2.1
FACILITY 03	3-3.1
FACILITY 05	3-4.1
FACILITY 06	3-5.1
FACILITY 08	3-6.1

INTRODUCTION

Rexene Products Company operates a facility in Pasadena, Texas which manufactures low density polyethylene and polypropylene resins. Several hazardous wastes are generated as a result of production of these two products.

Currently, Rexene has five active hazardous waste management units (HWMU). A sixth HWMU (Facility 01) previously underwent closure. Closure plans for each of the active units were prepared to comply with the closure requirements as outlined in 40 Code of Federal Regulations (CFR) Parts 264.110 through 264.116, 264.197 and 264.258.

Rexene intends to remove all waste residues, contaminated containment system components, contaminated subsoils and structures and equipment contaminated with wastes as outlined in the following closure plans. It is anticipated that the closures will take place concurrently at the time of final facility closure except for Facility 03 (Container Storage Area) which will remain open until closure has been completed on all other units. Facility 03 will receive any containerized wastes which may result from the closures of the other units. Rexene does not expect final closure of the facility until the year 2010.

FOULED XYLENE STORAGE TANK Facility 02 Tank TK-1903

1.0 INTRODUCTION

Facility 02 is a closed-top tank used to accumulate xylene contaminated with polypropylene or polyethylene polymer. The tank was placed in service in 1976 and has a maximum design capacity of 42,000 gallons. The tank is constructed of carbon steel, is insulated and has a diameter of 21.5 feet and a height of 16.02 feet.

2.0 PROCEDURES FOR CLOSING OF FACILITY 02

The following steps will be followed during closure proceedings for Facility 02:

- 1. Removal of residual waste:
- Collection of final rinsate sample:
- Removal of visually contaminated soils;
- 4. Collection of soil samples; and
- 5. Removal of contaminated soils.

Step 1 Removal of Residual Wastes

All residual wastes will be removed by using a high power wash or another appropriate method such as a detergent or chemical wash or sandblasting. The tank will be rinsed until all signs of contamination have been removed. All rinsate will be disposed at a facility authorized to receive such waste.

Step 2 Collection of Final Rinsate Sample

Rexene will collect a sample of the final rinsate following the rinsing of the tank. The rinsate will be analyzed for the following parameters:

- ° xylene
- ° ignitability

If the rinsate analysis indicates a concentration of xylene to be less than 1 ppm and does not exhibit the characteristic of ignitability, the tank will be considered clean. Step 1 will be repeated if necessary, until these conditions are satisfied.

Step 3 Removal of Visually Contaminated Soils

Prior to soil sampling, Rexene will inspect the soils surrounding Facility 02 to determine whether there have been releases. Rexene will remove all visually contaminated soils prior to sampling the site. All contaminated soils will be disposed at a facility authorized to dispose of such waste.

Step 4 Collection of Samples Surrounding the Tank

Rexene will sample the soils surrounding the tank to ensure that all waste constituents in the soil have been removed. Four soil samples will be taken in the areas surrounding the tank where signs of visible contamination were observed. This will ensure that the soils with the highest potential for contamination are sampled. If there are no visible signs of contamination, Rexene will sample the soils on all four sides of the tank in order to cover all areas that contamination might have occurred.

The four samples will be sampled at a depth of six inches and will be analyzed for xylene. These samples will be compared to a background sample taken from an area of the plant unaffected by waste management. If all four samples exhibit constituent concentrations that are less than the background constituent concentrations, Facility 08 will be considered "clean" closed.

Step 5 Removal of Contaminated Soils

If the analysis indicates that the xylene concentration is above the background standard, the remaining contaminated soils will be removed. In the areas where contamination occurs, Rexene will remove six inches of soil. The soil will then be resampled at a depth of six inches below the initial sampling point and will be re-analyzed for xylene. This process will be repeated until all contaminated soil is removed. All contaminated soils will be disposed of at a facility authorized to receive such waste unless it is determined that all soils cannot be practically removed. At that point Rexene will place all excavated soil back in the area of the tank and will close the tank as a landfill, following the procedures in Section 3.0 of this closure plan.

A groundwater monitoring system will be installed for post closure monitoring. The system will consist of a minimum of 1 upgradient and 3 downgradient monitor wells. The location of the wells will be submitted to the TWC at the time that is determined that Facility 02 will be closed as a landfill.

The survey data of the location of the tank will be submitted to the appropriate authorities in order to deed record the area as a solid waste landfill.

3.0 CONTINGENT CLOSURE PLAN AS A LANDFILL

Rexene will close Facility 02 as a landfill, pursuant to 40 CFR Part 264.310, if all contaminated soils cannot be practically removed. The tank will be recycled or reused if possible or cut into pieces and disposed of at an authorized facility. Rexene will cover the tank area with a cap which will minimize infiltration, which in turn, will prevent the migration of contaminants into the groundwater.

4.0 CONTINGENT POST-CLOSURE CARE PLAN

Rexene will perform post-closure care at Facility 02 for a period of 30 years after final closure. The post-closure care plan addresses the following:

- Monitoring the closed area
- Inspection of the closed area
- Maintenance of the closed area
- Post-closure cost estimate.

4.1 MONITORING THE CLOSED AREA

Groundwater monitoring will be conducted on a semi-annual basis. Rexene will monitor the groundwater for xylene. The parameter(s) selected for groundwater monitoring will be submitted to the TWC at the time that it is determined that Facility 02 must be closed as a landfill.

4.2 INSPECTION OF THE CLOSED AREA

Rexene will inspect the closed area on a semi-annual basis for the condition of the cover (e.g. cracks, uneven settlement), warning signs, monitor wells (e.g. missing locks) and benchmarks.

4.3 MAINTENANCE OF THE CLOSED AREA

The following post-closure maintenance activities will be implemented in this area as necessary:

- Cover system maintenance
- Groundwater monitoring system maintenance

Cover system maintenance will include maintaining the cover, benchmarks, and warning signs. The cover, benchmarks, and warning signs will be maintained on a semi-annual basis. The cover will be inspected for evidence of degradation (cracks or gaps). Rexene will repair the cover upon observance of degradation. The benchmarks will be inspected to determine

whether they have been damaged or removed. Rexene will repair or replace any damaged or missing benchmarks and re-survey the area. Warning signs will be inspected to ensure that the signs are legible. If the signs are damaged or missing, Rexene will repair or replace the signs.

Rexene will maintain all groundwater monitoring equipment and wells in an operational state to ensure that representative groundwater samples can be collected. Maintenance of the groundwater system will include replacing missing locks, replacing defective or broken surface seals and casing/covers and maintaining open well screens by redevelopment. Any monitor wells and/or associated parts will be replaced as required to maintain the system in an operative state.

4.4 POST-CLOSURE COST ESTIMATE

The post-closure cost estimate is included in Section 8.0 of this closure plan.

5.0 EQUIPMENT LIST AND EQUIPMENT DECONTAMINATION PROCEDURE

The equipment associated with Facility 02 closure activities will include the following:

- Sampling equipment
- High pressure wash
- Personnel safety equipment

All equipment will be decontaminated by using a high pressure wash. If all visible contamination cannot be removed using this method, another appropriate method, such as those described in Step 2 of Section 2.0 of this plan will be used. Any equipment that cannot be decontaminated will be disposed of at an authorized facility. Additionally, all water used in the decontamination of the equipment will be disposed of at a facility authorized to dispose of such waste.

6.0 NOTIFICATION OF CLOSURE ACTIVITIES

Rexene will notify the Texas Water Commission (TWC) of closure activities, in writing, at least 45 days prior to the date on which closure will commence. This will afford TWC personnel the opportunity to observe the closure activities and split samples.

The TWC recommends in Technical Guideline No. 3 that landfills be covered with a four-foot clay cap with a permeability of less than 1 X 10 cm/sec. Rexene may substitute an alternative cover material for the clay cap such as the following:

- ° Concrete
- ° Soil-admix

Rexene will provide a demonstration that the alternative it chooses will at least meet the same infiltration rate of a four-foot clay cover. Plans and specifications for the alternative cover system will be submitted to the TWC at the time Rexene determines that the tank must be closed as a landfill.

7.0 CLOSURE SCHEDULE

A closure schedule for Facility 02 is summarized in Table 1. For each step, the number of days specified represents the maximum time expected to be required to complete the task. Based on this schedule, the estimated completion of the closure of this unit will require 31 weeks after notification is provided to the TWC. This schedule does not account for any delays which may be caused by force majuere, including without limitations, fires, floods, riots, or strikes. If any of the aforementioned circumstances occur, the owner/operator will submit a written request to the Executive Director of the TWC to extend the time allowed for closure.

8.0 CLOSURE AND POST-CLOSURE COST ESTIMATES

Estimated closure costs are provided in Table 2. These estimates are based on the assumption that all wastes will be shipped off-site for disposal at an authorized facility. The total cost for closure of Facility 02 is estimated to be \$318,290.00.

The post-closure cost estimate is listed in Table 2 and is based on a thirty-year post-closure care period. The total post-closure cost estimate for Facility 02 is \$109,414.00.

9.0 CLOSURE CERTIFICATION

Once closure at Facility 02 has been completed, the unit will be inspected by the owner/operator and an independent registered Professional Engineer, authorized by the State of Texas. A certification report will be submitted to the TWC by both the owner/operator and by the independent Registered Professional Engineer which will include a summary of the closure activities performed, the locations of the soil sampling points, and the results of the analyses for all soil Additionally, the report will include and rinsate samples. results of visual inspections completed during closure and after closure completion. During the visual inspection during the closure activities, the Professional Engineer will also verify that the closure is being implemented as stated in the closure plan. The report will indicate that a final inspection was performed and which will include a description of the integrity of the closed unit.

Once the independent, registered Professional Engineer has completed the visual inspections, and has verified that the closure activities were performed in accordance with the approved closure plan, he will certify that closure of Facility 02 has been completed.

TABLE 1 CLOSURE SCHEDULE

CLOSURE ACTIVITY	DURATI (DAYS	
NOTIFY THE TEXAS WATER COMMISSION OF CLOSURE ACTIVITIES	45	
REMOVE WASTES FROM FACILITY 02	5	
DECONTAMINATE FACILITY 02	42	* .
TAKE FOUR BORINGS	1	
ANALYZE BORINGS AND RINSATE	35	
REMOVE CONTAMINATED SOILS	60	
CERTIFY AND SUBMIT REPORT OF CLOSURE ACTIVITIES	28	
TOTAL	216	Davs

TABLE 2 CLOSURE AND POST-CLOSURE COST ESTIMATE Facility 02

CLOSURE

DISPOSAL AND TRANSPORTATION COSTS	\$307,048.00
SAMPLING AND ANALYSIS COSTS	1,342.00
LABOR COSTS	8,800.00
CERTIFICATION OF CLOSURE COSTS	1,100.00
CLOSURE COSTS TOTAL	\$318,290.00
POST-CLOSURE	
*LANDFILL COVER COSTS	\$ 4,804.00
GROUNDWATER MONITORING WELLS INSTALLATION COSTS	13,200.00
SAMPLING AND ANALYTICAL COSTS	58,080.00
LABOR COSTS	13,860.00
MAINTENANCE COSTS	19,470.00
POST-CLOSURE COSTS TOTAL	\$109,414.00
CLOSURE AND POST-CLOSURE COSTS TOTAL	
\$318,290.00 + \$109,414.00 =	\$427,704.00

*Contingent closure as a landfill

Ć

HAZARDOUS WASTE CONTAINER STORAGE AREA Facility 03

1.0 INTRODUCTION

Facility 03 is an open concrete container storage area utilized for hazardous wastes generated from the polymer production processes. The storage area was placed in service in 1982 and has dimensions of 60 feet by 40 feet with 4" concrete containment curbs. The facility has a maximum design capacity of approximately 650 55-gallon drums. The wastes stored in Facility 03 include ignitable, corrosive, toxic and reactive materials. Waste constituents include the following:

- ° xylene
- ° heptane
- ° hexane
- ° chromium
- ° lead
- ° chlorinated solvents

2.0 PROCEDURES FOR CLOSING FACILITY 03

The closing of Facility 03 will include the following steps.

- 1. Removal of all containers;
- 2. Decontamination of the container storage area;
- 3. Collection of a final rinsate sample;
- 4. Inspection of the container storage area;
- 5. Inspection of soils surrounding Facility 03;
- 6. Collection of soil samples surrounding Facility 03; and
- 7. Removal of contaminated soils.

Step 1 Removal of All Waste Containers

Facility 03 has a maximum capacity of approximately 650 55-gallon containers with a total capacity of approximately 35,750 gallons. At the time of closure, all hazardous waste will be transported off-site to a facility authorized to receive hazardous waste.

Step 2 Decontamination of the Container Storage Area
Residual wastes will be removed from Facility 03 by high
pressure wash or by another appropriate method such as, but not
limited to, a detergent wash or a chemical wash. The container
storage area will be washed until all signs of visible
contamination are removed. The rinsate generated from the
removal process will be collected and transferred to a facility
authorized to receive such waste.

Step 3 Collection of Samples of the Final Rinsate

After the container storage area has been rinsed, the owner/
operator will collect a representative sample of the final
rinsate. The rinsate will be analyzed for the following
constituents:

- ° xylene
- heptane

- ° hexane
- ° chromium
- ° lead
- ° methylene chloride
- ° 1,1,1-trichlorethane

If the rinsate analyses indicate there is less than 1 ppm of the aforementioned constituents, the container storage area will be considered clean. If the rinsate analyses indicate that there is greater than 1 ppm of any constituent, Step 2 will be repeated until the 1 ppm clean-up criteria is met.

Step 4 Inspection of the Container Storage Area
Rexene will visually inspect the container storage area after
the decontamination procedure. This inspection will be
included in the certification report that will be submitted
after the closure activities have been completed. In the
certification report, the registered professional engineer will
indicate that all visual contamination has been removed and
will submit a statement indemnifying the integrity of the
containment system.

Step 5 Inspection of Soils Surrounding Facility 03
Rexene will inspect the soils surrounding Facility 03 to
determine whether there has been any soil contamination due to
the operation of the container storage area. In the area where
the soils are visually contaminated, Rexene will remove the
soils.

Step 6 Collection of Soil Samples Surrounding Facility 03
Rexene will sample the soils in the areas where visually contaminated soils were removed to ensure that all contamination has been removed. The samples will be taken at a depth of six inches and will be analyzed for the constituents previously mentioned. Metals will be analyzed for using the EP toxicity procedure.

These samples will be compared to a background sample taken from an area of the plant unaffected by waste management. If the samples exhibit concentrations that are less than or equal to background constituent concentrations, Facility 03 will be considered "clean" closed.

Step 7 Removal of Contaminated Soils

If the analysis of the soils around Facility 03 indicate any constituents at levels above the background standard, the contaminated soils will be removed. In the area where contamination is present, Rexene will remove six inches of soil. The area will then be resampled at a depth of six inches below the initial sampling point and will be re-analyzed. The process will be repeated until all contaminated soil is removed. All contaminated soils will be disposed of at an off-site facility authorized to receive such waste.

3.0 EQUIPMENT LIST AND EQUIPMENT DECONTAMINATION PROCEDURES

The equipment associated with the Facility 03 closure activities will include the following:

- ° Forklift
- * High pressure wash
- Personnel safety equipment
- Sampling equipment

The forklift will be decontaminated with a high pressure wash. If all visible contamination cannot be removed by the water wash, other appropriate methods will be used. Decontamination procedures for the personnel safety equipment and sampling equipment will include, but will not be limited to, a water wash or a detergent wash. Any equipment that cannot be decontaminated will be disposed of at an authorized facility. Additionally, all water used to decontaminate the equipment will be collected and transferred to a facility authorized to receive such waste.

4.0 NOTIFICATION OF CLOSURE ACTIVITIES

Rexene will notify the Texas Water Commission (TWC) of closure activities, in writing, at least 45 days prior to the date on which closure will commence. This will afford TWC personnel the opportunity to observe the closure activities and split samples.

5.0 CLOSURE SCHEDULE

A closure schedule for Facility 03 is summarized in Table 1. For each step, the number of days specified represents the maximum time expected to be required to complete the task. Based on this schedule, the completion of the closure of this unit will require 24 weeks after notification is provided to the TWC. This schedule does not account for any delays which may be caused by force majuere, including without limitations, fires, floods, riots, or strikes. If any of the aforementioned circumstances occur, the owner/operator will submit a written request to the Executive Director of the TWC to extend the time allowed for closure.

6.0 CLOSURE COSTS

Estimated closure costs are provided in Table 2. These estimates are based on the assumption that all wastes will be shipped off-site for disposal to an authorized TSD facility. The total cost for closure of Facility 03 is estimated to be \$261,556.00.

7.0 CLOSURE CERTIFICATION

Once closure at Facility 03 has been completed, the unit will be inspected by the owner/operator and an independent registered Professional Engineer, authorized by the State of Texas. A certification report will be submitted by both the owner/operator and by the independent registered Professional Engineer which will include a summary of the closure activities performed, the location of the soil samples and the results of the analyses for all of the soil samples. The report will also include the results of visual inspections completed during closure and after closure completion. Once the independent registered Professional Engineer has completed the visual inspections, and has verified that the closure activities were performed in accordance with the approved closure plan, he will certify that the closure has been completed.

TABLE 1 CLOSURE SCHEDULE

	DURATI	ON
CLOSURE ACTIVITY	(DAYS)
NOTIFY THE TEXAS WATER COMMISSION OF		
CLOSURE ACTIVITIES	45	-
REMOVE WASTES FROM FACILITY 03	5	
DECONTAMINATE FACILITY 03	5	
SAMPLE RINSATE FROM DECONTAMINATION ACTIVITIES	1	
VISUALLY INSPECT SURROUNDING AREAS FOR		
CONTAMINATION	1	
REMOVE CONTAMINATED SOILS	14	
ANALYZE SOIL AND RINSATE SAMPLES	35	
CERTIFY AND SUBMIT REPORT OF CLOSURE ACTIVITIES	28	
TOTAL	134	Days

TABLE 2 CLOSURE COST ESTIMATE

DISPOSAL AND TRANSPORTATION COSTS	\$234,436.00
SAMPLING AND ANALYTICAL COSTS	2,500.00
LABOR COSTS	3,520.00
CERTIFICATION OF CLOSURE COSTS	1,100.00
TOTAL	\$261,556.00

SLOP OIL STORAGE TANK Facility 05 Tank Tk-0401

1.0 INTRODUCTION

Facility 05 is a closed top tank used to accumulate waste oils which can periodically exhibit the characteristic of ignitability. The tank was placed in service in 1976 and has a maximum design capacity of 8400 gallons. The tank construction is carbon steel with a diameter of 12 feet and a height of 10 feet.

2.0 PROCEDURES FOR CLOSING OF FACILITY 05

The following steps will be followed during closure proceedings for Facility 05:

- 1. Removal of residual waste:
- 2. Collection of final rinsate sample;
- 3. Removal of visually contaminated soils;
- 4. Collection of soil samples; and
- 5. Removal of contaminated soils.

Step 1 Removal of Residual Wastes

All residual wastes will be removed by using a high power wash or another appropriate method such as a detergent or chemical wash or sandblasting. The tank will be rinsed until all signs of contamination have been removed. All rinsate will be disposed at a facility authorized to receive such waste.

Step 2 Collection of Final Rinsate Sample

Rexene will collect a sample of the final rinsate following the rinsing of the tank. The rinsate will be analyzed for the following parameters:

- ° hexane
- ° ignitability

If the rinsate analysis indicates a concentration of hexane to be less than 1 ppm and does not exhibit the characteristic of ignitability, the tank will be considered clean. Step 1 will be repeated if necessary, until these conditions are satisfied.

Step 3 Removal of Visually Contaminated Soils

Prior to soil sampling, Rexene will inspect the soils surrounding Facility 05 to determine whether there have been releases. Rexene will remove all visually contaminated soils prior to sampling the site. All contaminated soils will be disposed at a facility authorized to dispose of such waste.

Step 4 Collection of Samples Surrounding the Tank
Rexene will sample the soils surrounding the tank to ensure
that all waste constituents in the soil have been removed.
Four soil samples will be taken in the areas surrounding the
tank where signs of visible contamination were observed. This
will ensure that the soils with the highest potential for
contamination are sampled. If there are no visible signs of
contamination, Rexene will sample the soils on all four sides
of the tank in order to cover all areas that contamination
might have occurred.

The four samples will be sampled at a depth of six inches and will be analyzed for hexane. These samples will be compared to a background sample taken from an area of the plant unaffected by waste management. If all four samples exhibit constituent concentrations that are less than the background constituent concentrations, Facility 05 will be considered "clean" closed.

Step 5 Removal of Contaminated Soils

If the analysis indicates that the hexane concentration is above the background standard, the remaining contaminated soils will be removed. In the areas where contamination occurs, Rexene will remove six inches of soil. The soil will then be resampled at a depth of six inches below the initial sampling point and will be re-analyzed for hexane. This process will be repeated until all contaminated soil is removed. All contaminated soils will be disposed of at a facility authorized to receive such waste unless it is determined that all soils cannot be practically removed. At that point Rexene will place all excavated soil back in the area of the tank and will close the tank as a landfill, following the procedures in Section 3.0 of this closure plan.

A groundwater monitoring system will be installed for post closure monitoring. The system will consist of a minimum of 1 upgradient and 3 downgradient monitor wells. The location of the wells will be submitted to the TWC at the time that is determined that Facility 05 will be closed as a landfill.

The survey data of the location of the tank will be submitted to the appropriate authorities in order to deed record the area as a solid waste landfill.

3.0 CONTINGENT CLOSURE PLAN AS A LANDFILL

Rexene will close Facility 05 as a landfill, pursuant to 40 CFR Part 264.310, if all contaminated soils cannot be practically removed. The tank will be recycled or reused if possible or cut into pieces and disposed of at an authorized facility. Rexene will cover the tank area with a cap which will minimize infiltration, which in turn, will prevent the migration of contaminants into the groundwater.

4.0 CONTINGENT POST-CLOSURE CARE PLAN

Rexene will perform post-closure care at Facility 05 for a period of 30 years after final closure. The post-closure care plan addresses the following:

- Monitoring the closed area
- Inspection of the closed area
- Maintenance of the closed area
- Post-closure cost estimate.

4.1 MONITORING THE CLOSED AREA

Groundwater monitoring will be conducted on a semi-annual basis. Rexene will monitor the groundwater for hexane. The parameter(s) selected for groundwater monitoring will be submitted to the TWC at the time that it is determined that Facility 05 must be closed as a landfill.

4.2 INSPECTION OF THE CLOSED AREA

Rexene will inspect the closed area on a semi-annual basis for the condition of the cover (e.g. cracks, uneven settlement), warning signs, monitor wells (e.g. missing locks) and benchmarks.

4.3 MAINTENANCE OF THE CLOSED AREA

The following post-closure maintenance activities will be implemented in this area as necessary:

- Cover system maintenance
- Groundwater monitoring system maintenance

Cover system maintenance will include maintaining the cover, benchmarks, and warning signs. The cover, benchmarks, and warning signs will be maintained on a semi-annual basis. The cover will be inspected for evidence of degradation (cracks or gaps). Rexene will repair the cover upon observance of degradation. The benchmarks will be inspected to determine

whether they have been damaged or removed. Rexene will repair or replace any damaged or missing benchmarks and re-survey the area. Warning signs will be inspected to ensure that the signs are legible. If the signs are damaged or missing, Rexene will repair or replace the signs.

Rexene will maintain all groundwater monitoring equipment and wells in an operational state to ensure that representative groundwater samples can be collected. Maintenance of the groundwater system will include replacing missing locks, replacing defective or broken surface seals and casing/covers and maintaining open well screens by redevelopment. Any monitor wells and/or associated parts will be replaced as required to maintain the system in an operative state.

4.4 POST-CLOSURE COST ESTIMATE

The post-closure cost estimate is included in Section 8.0 of this closure plan.

5.0 EQUIPMENT LIST AND EQUIPMENT DECONTAMINATION PROCEDURE

The equipment associated with Facility 05 closure activities will include the following:

- Sampling equipment
- * High pressure wash
- Personnel safety equipment

All equipment will be decontaminated by using a high pressure wash. If all visible contamination cannot be removed using this method, another appropriate method, such as those described in Step 2 of Section 2.0 of this plan will be used. Any equipment that cannot be decontaminated will be disposed of at an authorized facility. Additionally, all water used in the decontamination of the equipment will be disposed of at a facility authorized to dispose of such waste.

6.0 NOTIFICATION OF CLOSURE ACTIVITIES

Rexene will notify the Texas Water Commission (TWC) of closure activities, in writing, at least 45 days prior to the date on which closure will commence. This will afford TWC personnel the opportunity to observe the closure activities and split samples.

The TWC recommends in Technical Guideline No. 3 that landfills be covered with a four-foot clay cap with a permeability of less than 1 X 10 cm/sec. Rexene may substitute an alternative cover material for the clay cap such as the following:

- ° Concrete
- ° Soil-admix

Rexene will provide a demonstration that the alternative it chooses will at least meet the same infiltration rate of a four-foot clay cover. Plans and specifications for the alternative cover system will be submitted to the TWC at the time Rexene determines that the tank must be closed as a landfill.

7.0 CLOSURE SCHEDULE

A closure schedule for Facility 05 is summarized in Table 1. For each step, the number of days specified represents the maximum time expected to be required to complete the task. Based on this schedule, the estimated completion of the closure of this unit will require 31 weeks after notification is provided to the TWC. This schedule does not account for any delays which may be caused by force majuere, including without limitations, fires, floods, riots, or strikes. If any of the aforementioned circumstances occur, the owner/operator will submit a written request to the Executive Director of the TWC to extend the time allowed for closure.

8.0 CLOSURE AND POST-CLOSURE COST ESTIMATES

Estimated closure costs are provided in Table 2. These estimates are based on the assumption that all wastes will be shipped off-site for disposal to an authorized TSD facility. The total cost for closure of facility 05 is estimated to be \$64,271.00.

The post-closure cost estimate is listed in Table 2. The estimate is based on a thirty year post-closure care period. The total post-closure cost estimate for Facility 05 is \$106,118.00.

9.0 CLOSURE CERTIFICATION

Once closure at Facility 05 has been completed, the unit will be inspected by the owner/operator and an independent registered Professional Engineer, authorized by the State of Texas. A certification report will be submitted to the TWC by both the owner/operator and by the independent registered Professional Engineer which will include a summary of the closure activities performed, the location of the soil borings, and the results of the analyses for all of the soil and rinsate samples. The report will also include the results of visual inspections completed during closure and after closure completion. Once the independent registered Professional Engineer has completed the visual inspections, and has verified that the closure activities were performed in accordance with the approved closure plan, he will certify that closure of the facility has been completed.

TABLE I CLOSURE SCHEDULE

	DURATION
CLOSURE ACTIVITY	(DAYS)
NOTIFY THE TEXAS WATER COMMISSION	
OF CLOSURE ACTIVITIES	45
REMOVE WASTES FROM THE FACILITY 05	5
DECONTAMINATE FACILITY 05	42
TAKE FOUR BORINGS	1
ANALYZE BORINGS AND RINSATE	35
REMOVE CONTAMINATED SOILS	60
CERTIFY AND SUBMIT REPORT OF CLOSURE ACTIVITIES	28
TOTAL	216 Davs

TABLE 2 CLOSURE AND POST-CLOSURE COST ESTIMATE Facility 05

CLOSURE

DISPOSAL AND TRANSPORTATION COSTS	\$ 53,029.00
SAMPLING AND ANALYSIS COSTS	1,342.00
LABOR COSTS	8,800.00
CERTIFICATION OF CLOSURE COSTS	1,100.00
CLOSURE COSTS TOTAL	\$ 64,271.00

POST-CLOSURE

*LANDFILL COVER COSTS	\$ 1,238.00
GROUNDWATER MONITORING WELLS INSTALLATION COSTS	13,200.00
SAMPLING AND ANALYSIS COSTS	58,080.00
LABOR COSTS	13,860.00
MAINTENANCE COSTS	19,470.00
POST-CLOSURE COSTS TOTAL	\$106,118.00
CLOSURE AND POST-CLOSURE COSTS TOTAL	

\$170,389.00

*Contingency Plan

\$64,271.00 + 106,118.00 =

PEROXIDE NEUTRALIZATION TANK Facility 06 Tank V-2304

1.0 INTRODUCTION

Facility 06 is an enclosed pressure vessel supported on 4 steel legs used to treat waste initiator (peroxides) in hexane from the polyethylene production process. The tank was placed in service in 1977 and has a design capacity of 550 gallons. The tank construction material is stainless steel with an exterior carbon steel jacket.

2.0 PROCEDURES FOR CLOSING OF FACILITY 06

The following steps will be followed during closure proceedings for Facility 06:

- Removal of residual waste;
- 2. Collection of final rinsate sample

Step 1 Removal of Residual Waste

All residual wastes will be removed by water wash followed by steaming or another appropriate method such as a detergent or chemical wash. The tank will be rinsed until all signs of contamination have been removed. All rinsate will be disposed at a facility authorized to receive such waste.

Step 2 Collection of Final Rinsate Sample

Rexene will collect a sample of the final rinsate following the rinsing of the tank. The rinsate will be analyzed for hexane and ignitability. Peroxides will not be included in the analysis since the water wash and steaming will hydrolyze the components due to their unstable and reactive nature. If the rinsate analysis indicates the concentration of hexane to be less than 1 ppm and does not exhibit the characteristic of ignitability, the tank will be considered clean. Step 1 will be repeated if necessary until these conditions are satisfied.

Since the area around this vessel is concrete with a drain to the chemical sewer which feeds to an off-site treatment facility, no soil contamination is expected. Soil samples from the closest point to the facility will be taken and analyzed and subsequently compared to a background sample. The background sample will be collected from an area unaffected by waste management. The soil samples will be analyzed for hexane and heptane which are the carriers of the peroxides and which would be constituents of most concern.

3.0 CONTINGENT CLOSURE PLAN FOR CLOSURE AS A LANDFILL

Rexene will close Facility 06 as a landfill if for some unexpected reason contamination around the facility is discovered during closure which cannot be practically removed. The tank vessel will be recycled or reused if possible or cut into pieces and disposed of at an authorized facility. Rexene will cover the area with a cap which will minimize infiltration, which in turn, will prevent migration of contaminants into the groundwater.

4.0 CONTINGENT POST-CLOSURE CARE PLAN

Rexene will perform post-closure care at Facility 06 for a period of 30 years after final closure. The post-closure care plan addresses the following:

- Monitoring the closed area
- Inspection of the closed area
- Maintenance of the closed area
- Post-closure cost estimate.

4.1 MONITORING THE CLOSED AREA

Groundwater monitoring will be conducted on a semi-annual basis. The parameter(s) selected for groundwater monitoring will be submitted to the TWC at the time that it is determined that Facility 06 must be closed as a landfill.

4.2 INSPECTION OF THE CLOSED AREA

Rexene will inspect the closed area on a semi-annual basis for the condition of the cover (e.g. cracks, uneven settlement), warning signs, monitor wells (e.g. missing locks) and benchmarks.

4.3 MAINTENANCE OF THE CLOSED AREA

The following post-closure maintenance activities will be implemented in this area as necessary:

- Cover system maintenance
- Groundwater monitoring system maintenance

Cover system maintenance will include maintaining the cover, benchmarks, and warning signs. The cover, benchmarks, and warning signs will be maintained on a semi-annual basis. The cover will be inspected for evidence of degradation (cracks or gaps). Rexene will repair the cover upon observance of degradation. The benchmarks will be inspected to determine whether they have been damaged or removed. Rexene will repair

or replace any damaged or missing benchmarks and re-survey the area. Warning signs will be inspected to ensure that the signs are legible. If the signs are damaged or missing, Rexene will repair or replace the signs.

Rexene will maintain all groundwater monitoring equipment and wells in an operational state to ensure that representative groundwater samples can be collected. Maintenance of the groundwater system will include replacing missing locks, replacing defective or broken surface seals and casing/covers and maintaining open well screens by redevelopment. Any monitor wells and/or associated parts will be replaced as required to maintain the system in an operative state.

4.4 POST-CLOSURE COST ESTIMATE

The post-closure cost estimate is included in Section 8.0 of this closure plan.

5.0 EQUIPMENT LIST AND EQUIPMENT DECONTAMINATION PROCEDURE

The equipment associated with Facility 06 closure activities will include the following:

- Sampling equipment
- * High pressure wash
- Personnel safety equipment

All equipment will be decontaminated by using a high pressure wash. If all visible contamination cannot be removed using this method, another appropriate method, such as those described in Step 2 of Section 2.0 of this plan will be used. Any equipment that cannot be decontaminated will be disposed of at an authorized facility. Additionally, all water used in the decontamination of the equipment will be disposed of at a facility authorized to dispose of such waste.

6.0 NOTIFICATION OF CLOSURE ACTIVITIES

Rexene will notify the Texas Water Commission (TWC) of closure activities, in writing, at least 45 days prior to the date on which closure will commence. This will afford TWC personnel the opportunity to observe the closure activities and split samples.

The TWC recommends in Technical Guideline No. 3 that landfills be covered with a four-foot clay cap with a permeability of less than 1 X 10 cm/sec. Rexene may substitute an alternative cover material for the clay cap such as the following:

- ° Concrete
- ° Soil-admix

Rexene will provide a demonstration that the alternative it chooses will at least meet the same infiltration rate of a four-foot clay cover. Plans and specifications for the alternative cover system will be submitted to the TWC at the time Rexene determines that the tank must be closed as a landfill.

7.0 CLOSURE SCHEDULE

A closure schedule for Facility 06 is summarized in Table 1. For each step, the number of days specified represents the maximum time expected to be required to complete the task. Based on this schedule, the estimated completion of the closure of this unit will require 31 weeks after notification is provided to the TWC. This schedule does not account for any delays which may be caused by force majuere, including without limitations, fires, floods, riots, or strikes. If any of the aforementioned circumstances occur, the owner/operator will submit a written request to the Executive Director of the TWC to extend the time allowed for closure.

8.0 CLOSURE AND POST-CLOSURE COST ESTIMATES

Estimated closure costs are provided in Table 2. These estimates are based on the assumption that all wastes will be shipped off-site for disposal to an authorized TSD facility. The total cost for closure of Facility 06 is estimated to be \$11,684.00.

The post-closure cost estimate is listed in Table 2. The estimate is based on a thirty year post-closure care period. The total post-closure cost estimate for Facility 06 is \$104,723.00.

9.0 CLOSURE CERTIFICATION

Once closure at Facility 06 has been completed, the unit will be inspected by the owner/operator and an independent registered Professional Engineer, authorized by the State of Texas. A certification report will be submitted to the TWC by both the owner/operator and by the independent registered Professional Engineer which will include a summary of the closure activities performed, the location of the soil borings, and the results of the analyses for all of the soil and rinsate The report will also include the results of visual samples. inspections completed during closure and after closure completion. Once the independent registered Professional Engineer has completed the visual inspections, and has verified that the closure activities were performed in accordance with the approved closure plan, he will certify that closure of the facility has been completed.

TABLE 1 CLOSURE SCHEDULE

CLOSURE ACTIVITY	DURATION (DAYS)	
NOTIFY THE TEXAS WATER COMMISSION		
OF CLOSURE ACTIVITIES	45	
REMOVE WASTES FROM THE FACILITY 06	5	
DECONTAMINATE FACILITY 06	42	
SAMPLE SOIL CLOSEST TO FACILITY	1	
ANALYZE SOIL SAMPLES RINSATE	35	
REMOVE CONTAMINATED SOILS IF NECESSARY	60	
CERTIFY AND SUBMIT REPORT OF CLOSURE ACTIVITIES	28	
TOTAL	216 Day	٤

TABLE 2 CLOSURE AND POST-CLOSURE COST ESTIMATE FACILITY 06

CLOSURE

DIGDOGAT AND MDANGDODES TANK	
DISPOSAL AND TRANSPORTATION COSTS	\$ 442.00
SAMPLING AND ANALYSIS COSTS	1,342.00
LABOR COSTS	8,800.00
CERTIFICATION OF CLOSURE COSTS	1,100.00
CLOSURE COSTS TOTAL	\$ 11,684.00
POST-CLOSURE	
*LANDFILL COVER COSTS	\$ 113.00
GROUNDWATER MONITORING WELLS INSTALLATION COSTS	13,200.00
SAMPLING AND ANALYSIS COSTS	58,080.00
LABOR COSTS	13,860.00
MAINTENANCE COSTS	19,470.00
POST-CLOSURE COSTS TOTAL	\$104,723.00
CLOSURE AND POST-CLOSURE COSTS TOTAL	
\$11,684.00 + \$104,723.00 =	\$116,407.00

*Contingency Plan

FOULED SOLVENT STORAGE TANK Facility 08 Tank TK 2903

1.0 INTRODUCTION

Facility 08 is a closed top tank used to accumulate xylene or naphtha contaminated with polyethylene polymer. The tank was originally placed in service in 1976 and has a maximum design capacity of approximately 18,000 gallons. The tank construction material consists of carbon steel and has a diameter of 12 feet and a height of 20 feet. Facility 08 is currently inactive awaiting the installation of secondary containment meeting the requirements of 40 CFR § 264 Subpart J - Tank Systems.

2.0 PROCEDURES FOR CLOSING OF FACILITY 08

The following steps will be followed during closure proceedings for Facility 08:

- Removal of residual waste;
- Collection of final rinsate sample;
- Removal of visually contaminated soils;
- 4. Collection of soil samples; and
- 5. Removal of contaminated soils.

Step 1 Removal of Residual Wastes

All residual wastes will be removed by using a high power wash or another appropriate method such as a detergent or chemical wash or sandblasting. The tank will be rinsed until all signs of contamination have been removed. All rinsate will be disposed at a facility authorized to receive such waste.

Step 2 Collection of Final Rinsate Sample

Rexene will collect a sample of the final rinsate following the rinsing of the tank. The rinsate will be analyzed for the following parameters:

- ° xylene
- ° naphtha
- ° ignitability

If the rinsate analysis indicates a concentration of xylene and naphtha to be less than 1 ppm and does not exhibit the characteristic of ignitability, the tank will be considered clean. Step 1 will be repeated if necessary, until these conditions are satisfied.

Step 3 Removal of Visually Contaminated Soils

Prior to soil sampling, Rexene will inspect the soils surrounding Facility 08 to determine whether there have been releases. Rexene will remove all visually contaminated soils prior to sampling the site. All contaminated soils will be disposed at a facility authorized to dispose of such waste.

Step 4 Collection of Samples Surrounding the Tank
Rexene will sample the soils surrounding the tank to ensure
that all waste constituents in the soil have been removed.
Four soil samples will be taken in the areas surrounding the
tank where signs of visible contamination were observed. This
will ensure that the soils with the highest potential for
contamination are sampled. If there are no visible signs of
contamination, Rexene will sample the soils on all four sides
of the tank in order to cover all areas that contamination
might have occurred.

The four samples will be sampled at a depth of six inches and will be analyzed for xylene and naphtha. These samples will be compared to a background sample taken from an area of the plant unaffected by waste management. If all four samples exhibit constituent concentrations that are less than the background constituent concentrations, Facility 08 will be considered "clean" closed.

Step 5 Removal of Contaminated Soils

If the analysis indicates that the xylene or naphtha concentration is above the background standard, the remaining contaminated soils will be removed. In the areas where contamination occurs, Rexene will remove six inches of soil. The soil will then be resampled at a depth of six inches below the initial sampling point and will be re-analyzed for xylene and/or naphtha. This process will be repeated until all contaminated soil is removed. All contaminated soils will be disposed of at a facility authorized to receive such waste unless it is determined that all soils cannot be practically removed. At that point Rexene will place all excavated soil back in the area of the tank and will close the tank as a landfill, following the procedures in Section 3.0 of this closure plan.

A groundwater monitoring system will be installed for post closure monitoring. The system will consist of a minimum of 1 upgradient and 3 downgradient monitor wells. The location of the wells will be submitted to the TWC at the time that is determined that Facility 08 will be closed as a landfill.

The survey data of the location of the tank will be submitted to the appropriate authorities in order to deed record the area as a solid waste landfill.

3.0 CONTINGENT CLOSURE PLAN AS A LANDFILL

Rexene will close Facility 08 as a landfill, pursuant to 40 CFR Part 264.310, if all contaminated soils cannot be practically removed. The tank will be recycled or reused if possible or cut into pieces and disposed of at an authorized facility. Rexene will cover the tank area with a cap which will minimize infiltration, which in turn, will prevent the migration of contaminants into the groundwater.

4.0 CONTINGENT POST-CLOSURE CARE PLAN

Rexene will perform post-closure care at Facility 08 for a period of 30 years after final closure. The post-closure care plan addresses the following:

- Monitoring the closed area
- Inspection of the closed area
- Maintenance of the closed area
- Post-closure cost estimate.

4.1 MONITORING THE CLOSED AREA

Groundwater monitoring will be conducted on a semi-annual basis. Rexene will monitor the groundwater for xylene and/or naphtha. The parameter(s) selected for groundwater monitoring will be submitted to the TWC at the time that it is determined that Facility 08 must be closed as a landfill.

4.2 INSPECTION OF THE CLOSED AREA

Rexene will inspect the closed area on a semi-annual basis for the condition of the cover (e.g. cracks, uneven settlement), warning signs, monitor wells (e.g. missing locks) and benchmarks.

4.3 MAINTENANCE OF THE CLOSED AREA

The following post-closure maintenance activities will be implemented in this area as necessary:

- Cover system maintenance
- Groundwater monitoring system maintenance

Cover system maintenance will include maintaining the cover, benchmarks, and warning signs. The cover, benchmarks, and warning signs will be maintained on a semi-annual basis. The cover will be inspected for evidence of degradation (cracks or gaps). Rexene will repair the cover upon observance of degradation. The benchmarks will be inspected to determine

whether they have been damaged or removed. Rexene will repair or replace any damaged or missing benchmarks and re-survey the area. Warning signs will be inspected to ensure that the signs are legible. If the signs are damaged or missing, Rexene will repair or replace the signs.

Rexene will maintain all groundwater monitoring equipment and wells in an operational state to ensure that representative groundwater samples can be collected. Maintenance of the groundwater system will include replacing missing locks, replacing defective or broken surface seals and casing/covers and maintaining open well screens by redevelopment. Any monitor wells and/or associated parts will be replaced as required to maintain the system in an operative state.

4.4 POST-CLOSURE COST ESTIMATE

The post-closure cost estimate is included in Section 8.0 of this closure plan.

5.0 EQUIPMENT LIST AND EQUIPMENT DECONTAMINATION PROCEDURE

The equipment associated with Facility 08 closure activities will include the following:

- Sampling equipment
- * High pressure wash
- Personnel safety equipment

All equipment will be decontaminated by using a high pressure wash. If all visible contamination cannot be removed using this method, another appropriate method, such as those described in Step 2 of Section 2.0 of this plan will be used. Any equipment that cannot be decontaminated will be disposed of at an authorized facility. Additionally, all water used in the decontamination of the equipment will be disposed of at a facility authorized to dispose of such waste.

6.0 NOTIFICATION OF CLOSURE ACTIVITIES

Rexene will notify the Texas Water Commission (TWC) of closure activities, in writing, at least 45 days prior to the date on which closure will commence. This will afford TWC personnel the opportunity to observe the closure activities and split samples.

The TWC recommends in Technical Guideline No. 3 that landfills be covered with a four-foot clay cap with a permeability of less than 1 x 10 $^{-7}$ cm/sec. Rexene may substitute an alternative cover material for the clay cap such as the following:

- ° Concrete
- ° Soil-admix

Rexene will provide a demonstration that the alternative it chooses will at least meet the same infiltration rate of a four-foot clay cover. Plans and specifications for the alternative cover system will be submitted to the TWC at the time Rexene determines that the tank must be closed as a landfill.

7.0 CLOSURE SCHEDULE

A closure schedule for Facility 08 is summarized in Table 1. For each step, the number of days specified represents the maximum time expected to be required to complete the task. Based on this schedule, the estimated completion of the closure of this unit will require 31 weeks after notification is provided to the TWC. This schedule does not account for any delays which may be caused by force majuere, including without limitations, fires, floods, riots, or strikes. If any of the aforementioned circumstances occur, the owner/operator will submit a written request to the Executive Director of the TWC to extend the time allowed for closure.

8.0 CLOSURE AND POST-CLOSURE COST ESTIMATES

Estimated closure costs are provided in Table 2. These estimates are based on the assumption that all wastes will be shipped off-site for disposal to an authorized TSD facility. The total cost for closure of Facility 08 is estimated to be \$139,720.00.

The post-closure cost estimate is listed in Table 2. The estimate is based on a thirty year post-closure care period. The total post-closure cost estimate for Facility 08 is \$109,366.00.

9.0 CLOSURE CERTIFICATION

Once closure at Facility 08 has been completed, the unit will be inspected by the owner/operator and an independent registered Professional Engineer, authorized by the State of Texas. A certification report will be submitted to the TWC by both the owner/operator and by the independent registered Professional Engineer which will include a summary of the closure activities performed, the location of the soil borings, and the results of the analyses for all of the soil and rinsate The report will also include the results of visual inspections completed during closure and after closure completion. Once the independent registered Professional Engineer has completed the visual inspections, and has verified that the closure activities were performed in accordance with the approved closure plan, he will certify that closure of the facility has been completed.

TABLE 1 CLOSURE SCHEDULE

	DURATION	
CLOSURE ACTIVITY	(DAYS)	
NOTIFY THE TEXAS WATER COMMISSION OF		
CLOSURE ACTIVITIES	45	
REMOVE WASTES FROM THE FACILITY 08	5	
DECONTAMINATE FACILITY 08	42	
TAKE FOUR BORINGS	1	
ANALYZE BORINGS AND RINSATE	35	
REMOVE CONTAMINATED SOILS	60	
CERTIFY AND SUBMIT REPORT OF CLOSURE ACTIVITIES	28	
TOTAL	216 Days	

TABLE 2 CLOSURE AND POST-CLOSURE COST ESTIMATE FACILITY 08

CLOSURE

DISPOSAL AND TRANSPORTATION COSTS SAMPLING AND ANALYSIS COSTS	1,342.00
LABOR COSTS	8,800.00
CERTIFICATION OF CLOSURE COSTS	1,100.00
CLOSURE COSTS TOTAL	\$139,720.00

POST CLOSURE

POST-CLOSURE COSTS TOTAL			\$109,366.00
MAINTENANCE COSTS			
LABOR COSTS			19,470.00
SAMPLING AND ANALYSIS COSTS			13,860.00
			48,080.00
*LANDFILL COVER COSTS GROUNDWATER MONITORING WELLS	INSTALLATION	COSTS	13,200.00
COSTS			\$ 4,756.00

CLOSURE AND POST-CLOSURE COSTS TOTAL

		\$ <u>249.086.00</u>
\$139,720.00 + \$109,366.00 =		424574
S139,720.00 1 9±057		

*Contingency Plan